






MONTANA

S1D




No.	L[mm]	W[mm]	H[mm]	PCS	Box
1	1940	50	22	1	1/2
2	1940	50	22	1	1/2
3	1940	400	15	1	1/2
4	1940	400	15	1	1/2
5	395	775	15	1	1/2
6	503	430	22	1	2/2
7	470	371	15	1	2/2
8	470	400	15	1	2/2
9	469	60	15	1	2/2
10	497	1900	2,5	1	1/2
11	470	70	28	1	2/2
12	395	1070	15	1	1/2
13	470	371	15	3	2/2




1

A1 x 8









Ø8x35mm

B1 x 8




Ø5x38mm





2

B1 x 8












Ø5x38mm







3




Z6 x4
Ø35mm, 90°






4






5






6






7






8






9






10





11







12






13



14




15




16

W2x8





Ø3,5x16mm





Z6-bx4



Ø35 mm, 90°










17



18



T4 x1
75x28x16 mm

W2 x2
Ø3,5x16mm



- I**
- II**
- III**
- IV**
- V**
- VI**

19



20

